CofC

PATENT



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent Number: 6,977,922

Issued: December 20, 2005

Name of Patentee: Blanset, et al.

Title of Invention: Systems and Methods for Automatically Configuring Cross-Connections

in a Digital Subscriber Line Access Multiplexer (DSLAM)

Commissioner for Patents P.O. Box 1450 Alexandria, Virginia 22313-1450

Certificate

MAR 2 8 2006

Attention:

Decision and Certificate of Correction

Branch of the Patent Issue Division

of Correction

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR PTO MISTAKE (37 C.F.R. § 1.322(a))

1. Attached, in duplicate, is PTO/SB/44 (also Form PTO-1050), with at least one copy being suitable for printing.

NOTE: Form PTO-1050 (or PTO/SB/44), using the column and line number in the printed patent, should be used exclusively regardless of the length or complexity of the subject matter. M.P.E.P § 1485, 7th ed.

NOTE: The patent grant should be retained by the patentee. The PTO does not attach the certificate of correction to the patentee's copy of the patent. The patent grant will be returned to the patentee if submitted.

M.P.E.P. § 1485.

2. The exact page and line number where the errors are shown correctly in the application file are:

Specification, page 8, line 10 Specification, page 12, line 13 Specification, page 18, line 16 Originally Filed Claims, page 26, line 1 3. Please send the Certificate to:

Name: Scott A. Horstemeyer

Address:

Thomas, Kayden,

Horstemeyer, & Risley, L.L.P. 100 Galleria Parkway, Suite 1750

Atlanta, Georgia 30339

SIGNATURE OF PRACTITIONER

Karen G. Hazzah, Reg. No. 48,472

(type or print name of practitioner)

Tel. No.: (770) 933-9500

Thomas, Kayden, Horstemeyer, & Risley, L.L.P. 100 Galleria Parkway, Suite 1750 Atlanta, Georgia 30339

Customer No.: 24504

NOTE: The certificate of correction, under 35 U.S.C. 254, may be issued at the request of the patentee or [the patentee's] assignee." 37 C.F.R. §1.322(a). The certificate of correction can be signed by the attorney of record who acts on behalf of the inventor(s) or assignee(s).

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Patent No.: 6,977,922

Dated:

December 20, 2005

Inventor(s): Blanset, et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below

Column 5

Line 47, delete "Tn" and insert "In".

Column 8

Line 24, delete "FIG. 5.)".

Column 12

Line 17, delete "VPI!VCI" and insert "VPI/VCI".

Column 16

Line 9, delete "17" and insert "15,".

MAILING ADDRESS OF SENDER:

THOMAS, KAYDEN, HORSTEMEYER & RISLEY, L.L.P. 100 Galleria Parkway, Suite 1750 Atlanta, Georgia 30339

No. of additional copies

PTO/SB/44 (04-04)

Patent No.: 6,977,922

This collection of information is required by 37 CFR 1.33. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.13. The collection is estimated to take 1 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Office, U.S. Patent and Trademark Office, P.O. Box 1450, Arlington, Virginia 22313-1450 DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (also form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Patent No.: 6,977,922

Dated:

December 20, 2005

Inventor(s): Blanset, et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below

Column 5

Line 47, delete "Tn" and insert "In".

Column 8

Line 24, delete "FIG. 5.)".

Column 12

Line 17, delete "VPI!VCI" and insert "VPI/VCI".

Column 16

Line 9, delete "17" and insert "15,".

MAILING ADDRESS OF SENDER:

THOMAS, KAYDEN, HORSTEMEYER & RISLEY, L.L.P. 100 Galleria Parkway, Suite 1750 Atlanta, Georgia 30339

No. of additional copies

Patent No.: 6,977,922

This collection of information is required by 37 CFR 1.33. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.13. The collection is estimated to take 1 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Office, U.S. Patent and Trademark Office, P.O. Box 1450, Arlington, Virginia 22313-1450 DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.



CERTIFICATE OF MAILING

I hereby certify that this correspondence is being deposited with the U.S. Postal Service as first class mail in an envelope addressed to:

ATTN: Certificate of Corrections Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

on March 21, 2006

Anne Antonoff

In re Patent of:

Blanset, et al.

U.S. Patent No:

6,977,922

Issue Date:

December 20, 2005

Title: Systems and Methods for Automatically Configuring Cross-Connections In A Digital Subscriber Line Access Multiplexer (DSLAM)

Our Reference Number: 061607-1610

The following is a list of documents enclosed:

Return Postcard
Request for Certificate of Correction
Certificate of Correction (& Original Duplicate)

00079387.DOC